



- 1.The motor is not welded,the outer surface is secured with cable ties.
- 2.The motor is not potted(vernished)
- 3.The axial dimension does not include the height of the weld joint.

DMM-110-A